Table of Contents

Introduction 1

Chapter 1
General 4

Chapter 2
Material imperfections—Stress Birefringence 14

Chapter 3
Material imperfections—Bubbles and inclusions 17

Chapter 4
Material imperfections—Inhomogeneity and striae 20

Chapter 5
Surface form tolerances 23

Chapter 6
Centring tolerances 35

Chapter 7
Surface imperfection tolerances 45

Chapter 8
Surface texture 50

Chapter 9
Surface treatment and coating 63

Chapter 10
Tabular form 67

Chapter 11
Non-toleranced data 71

Chapter 12
Aspheric surfaces 75

Chapter 13
Laser irradiation damage threshold 80

Glossary for ISO 10110 User's Guide 84